

Inspection Photos

API: 071-06130

Operator: OGRIS OPERATING LLC

Inspection Date: 7/7/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 1. Facing southwest along the main road. There is vehicle rutting along the main road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 2. Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 3. Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 4. Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 5. Stormwater is not directed toward the culvert (at red arrow) causing stormwater to accumulate on the road. Areas of rutting need to be stabilized. Previous corrective action was not performed



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 6. Facing toward the location. Erosion is occurring along side of the road at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021

Inspection Photos



Photo 7. Facing toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06130 | Date: 7/7/2021