

# Inspection Photos

API: 125-07961

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/13/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021

## Inspection Photos



**Photo 1.** Facing northeast toward a meter shed which is approximately 500' south of the well site. All equipment should have been removed within 3 months of plugging the well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021



## Inspection Photos



**Photo 2.** There is a lack of vegetation growth around the meter shed. Historic aerial images show a possible pit at this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021

## Inspection Photos



**Photo 3.** Facing north at the location. This area has no vegetation growth on approximately 25'x10' area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021



## Inspection Photos



**Photo 4.** Facing southeast at the location. This area has no vegetation growth on approximately 25'x10' area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021



## Inspection Photos



**Photo 5.** Facing west at the location. The area outlined under the blue line, consists of undesirable weeds of Kochia and Cheat grass.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021



## Inspection Photos



**Photo 6.** Facing east at the surrounding undisturbed pasture which shows desirable perennial vegetation consisting of Western wheat grass, Intermediate wheat grass, among other species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 125-07961 | Date: 7/13/2021