

# Inspection Photos

API: 121-07019

Operator: PUCKETT-WARREN OIL CO

Inspection Date: 7/14/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021

## Inspection Photos



**Photo 1.** Facing northwest at the associated pit which is located 600' southwest of the wellsite. The crop has not re-establish in the area of the former pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021

## Inspection Photos



**Photo 2.** Facing north at the associated pit which is located 600' southwest of the wellsite. The crop has not re-establish in the area of the former pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021

## Inspection Photos



**Photo 3.** Drone aerial photo overlooking the pit area which shows areas with no crop growth. The red arrow points to the well site located 600' northeast of the former pit area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021

## Inspection Photos



**Photo 4.** Drone aerial photo facing southwest overlooking the pit area which shows areas with no crop growth.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021

## Inspection Photos



**Photo 5.** Drone aerial photo overlooking the well sites which appears to have re-established a uniform crop cover. The red arrow points to the pit area located 600' southwest of the former well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 121-07019 | Date: 7/14/2021