

Inspection Photos

API: 125-06688

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 7/15/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/15/2021

Inspection Photos



Photo 1. Facing north toward the location. There is an area 30'x30' with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/15/2021

Inspection Photos



Photo 2. Facing east at the location. Arrow points to List B Noxious weeds; Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/15/2021

Inspection Photos



Photo 3. This area at the well site is approximately 30'x30' with no vegetation growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/15/2021

Inspection Photos



Photo 4. Facing southwest toward the surrounding undisturbed CRP pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06688 | Date: 7/15/2021