

Inspection Photos
Location Name: Newton 1
Location ID: 319025



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Newton 1
Location ID: 319025



Photo 3 TB sign



Photo 4 TB

Inspection Photos
Location Name: Newton 1
Location ID: 319025



Photo 5 Horizontal Heated Separator



Photo 6 ECD

Inspection Photos
Location Name: Newton 1
Location ID: 319025



Photo 7 Gas Meter Run




Photo 8 card in meter house indicates that calibration is not current.