

Inspection Photos
Location Name: Anschutz State 5-62-27_34 #SESE-22
Location ID: 421665



Photo 1 – 5-62-27-0857BH Wellhead – Stained Soil




Photo 2 – Windmill 04-22H Wellhead – Stained Soil

Inspection Photos

Location Name: Anschutz State 5-62-27_34 #SESE-22

Location ID: 421665



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign

Inspection Photos
Location Name: Anschutz State 5-62-27_34 #SESE-22
Location ID: 421665



Photo 5 – Day Tanks



Photo 6 – Separators

Inspection Photos

Location Name: Anschutz State 5-62-27_34 #SESE-22

Location ID: 421665



Photo 7 – ECD