

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #4499 from entrance to location.



Photo #4500 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #4501 No battery sign located at the tank battery.



Photo #4502 Multiple places with undesirable plant species.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENYEART-67S95W /16NWNW

Location ID: 334761



Photo #4503 Multiple places with undesirable plant species.