

Inspection Photos
Location Name: Ptasynski 3
Location ID: 312952



Photo 1. Overview of location taken facing east.



Photo 2. Wellhead sign faded and illegible.



Inspection Photos
Location Name: Ptasynski 3
Location ID: 312952



Photo 3. No bradenhead access apparent.



Photo 4. Pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources