

Inspection Photos
Location Name: Rusco 33-23
Location ID: 306621



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos
Location Name: Rusco 33-23
Location ID: 306621



Photo 3: Disconnected/unused automation



Photo 4: Tank Battery

