

Inspection Photos

API: 071-06811

Operator: WAPITI OPERATING LLC

Inspection Date: 7/22/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06811 | Date: 7/22/2021

Inspection Photos



Photo 1. Facing northeast at the Lorencito creek crossing. Storm event has caused damage to the road and culverts.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 7/22/2021

Inspection Photos



Photo 2. The culvert inlets are eroded and will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 7/22/2021

Inspection Photos



Photo 3. The culvert outlets are eroded and will need to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06811 | Date: 7/22/2021