

Final Reclamation Inspection

June 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 319948

Inspection Document #: 697503076

Weld County, CO

SWNE Section 5 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CHAMPLIN 78 AMOCO D #1

Location ID: 319948



Photo 1. 2019 aerial imagery illustrates the well location (tank battery included) and the well location access road (highlighted in red).



Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 2. Photo taken from the location, facing South. Photo illustrates not all equipment has been removed from location.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 3. Photo taken from the location, facing Southwest. Photo illustrates the concrete pad still has not been removed which appeared to be used for oil and gas operations.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 4. Photo taken from the location, facing South. Photo illustrates flowering noxious weeds, Scotch thistle.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 5. Photo taken from the western well location access road, facing East. Photo illustrates the access road is evident with little to no desirable vegetation establishment throughout the entire access road.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 6. Photo taken from the central well location access road, facing East. See comments under Photo 5.

Inspection Photos
Location Name: CHAMPLIN 78 AMOCO D #1
Location ID: 319948



Photo 7. Close up photo taken from the location. Photo illustrates the establishment of desirable perennial species, Buffalo grass, but the location will remain in-process.