

Inspection Photos

7/21/2021

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 324457

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324457



Photo 1: Photo taken from the west end of the Location, facing east. Photo shows Location has not been reclaimed in accordance with 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324457



Photo 2: Photo taken from the east end of the Location, facing west. Photo shows Location has not been reclaimed in accordance with 1004 Rules.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324457



Photo 3: Photo taken from the southeast end of the Location. Photo shows examples of areas where gravel has not been removed and area reclaimed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 324457



Photo 4: Photo taken from the southeast end of the Location. Photo shows example of noxious weeds on Location. Additional management activities appear to have been conducted; however, it was unclear at the time of the inspection if management has been adequate; noxious weeds remain evident.

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 324457



July 21, 2021
39.1199894N 107.48560627W

Photo 5: Photo shows access road has not been reclaimed in accordance with 1004 Rules.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources