

Final Reclamation Inspection

June 16, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 320364

Inspection Document #: 697503078

Weld County, CO

SWSE Section 5 T1S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 1. 2019 aerial imagery illustrates the well location, well location access road and associated tank battery.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 2. Photo taken from a section of the well location access road, facing North. Photo illustrates a flowering noxious weed, Scotch thistle.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 3. Photo taken from the well location, facing North. Photo illustrates the well location appears reflective of reference area vegetative levels.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 4. Photo taken from a portion of the well location access road, facing South. Photo illustrates desirable establishment but will remain in-process.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 5. Photo taken from the associated tank battery, facing South. Photo illustrates desirable establishment but will remain in-process.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 6. Photo taken from the associated tank battery, facing North. See comments under Photo 5.

Inspection Photos
Location Name: dreyer #1
Location ID: 320364



Photo 7. Reference photo taken east of the associated tank battery, facing Northeast.