

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36SWNW

Location ID: 335096



Photo #4551 from entrance to location.



Photo #4552 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36SWNW

Location ID: 335096



Photo #4553 Multiple wellhead signs weathered and not legible.



Photo #4554 Multiple wellhead signs weathered and not legible.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S96W /36SWNW

Location ID: 335096



Photo #4555 Battery sign weathered and not legible.




Photo #4556 Sediment and debris encroaching on production equipment.

