

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #4575 from entrance to location.



Photo #4576 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3572 from inspection #699802961 conducted on 4/21/21.



Photo #4577 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3574 from inspection #699802961 conducted on 4/21/21.



Photo #4578 No form of tracking BMP located at the entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY-67S96W /23SESW

Location ID: 334579



Photo #3574 from inspection #699802961 conducted on 4/21/21.