

Inspection Photos

API: 071-08256

Operator: OGRIS OPERATING LLC

Inspection Date: 7/29/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08256 | Date: 7/29/2021

Inspection Photos



Photo 1. Facing east along the main road near the location. The vehicle rutting in this area needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08256 | Date: 7/29/2021

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08256 | Date: 7/29/2021

Inspection Photos



Photo 3. There was an oil leak at the engine causing oil to spill across the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08256 | Date: 7/29/2021