

# Final Reclamation Inspection

July 28, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323140

Inspection Document #: 697503098

Weld County, CO

NWNW Section 7 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HAYTHORN #1  
Location ID: 323140



**Photo 1.** Google Earth aerial imagery taken 4/12/2006 taken during active operations. Photo illustrates the well location, well location access road and the offsite tank battery location.

Inspection Photos  
Location Name: HAYTHORN #1  
Location ID: 323140



**Photo 2.** Drone aerial imagery taken from the wellhead, facing West. Photo illustrates the well location and well location access road are reflective of reference areas.





Inspection Photos  
Location Name: HAYTHORN #1  
Location ID: 323140



07.28.2021 13:29

**Photo 3.** Photo taken from the associated offsite tank battery, facing North. Photo illustrates final reclamation has not been performed.



Inspection Photos  
Location Name: HAYTHORN #1  
Location ID: 323140



**Photo 4.** Photo taken from the associated offsite tank battery, facing South. See comments under Photo 3.