

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Nearest road not on sign.



Weeds covering location.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Sediment movement and riling from unstable slope.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



No battery sign at tank battery.



Sediment moving on to location.



UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Sediment and riling moving off location.



Erosion of access road.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Road ditch need maintained.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Erosion of access road. Washing away roadway.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Erosion of access road. Washing away roadway.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Erosion of access road. Washing away roadway.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



**Storm water from road ditch and low water crossing
washing away road side.**

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Erosion of access road. Washing away roadway.

**UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987**



Erosion of access road. Washing away roadway.

UTAH GAS OP LTD DBA UTAH GAS CORP
FEDERAL-62S101W 27NESW
Location # 314987



Road ditch needs maintained.



Movement of sediment across access road.