

# Final Reclamation Inspection

July 30, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 310650

Inspection Document #: 697503114

Weld County, CO

SWNW Section 18 T6N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: KOCHERT #12-18  
Location ID: 310650



**Photo 1.** Google Earth aerial imagery taken 6/19/2014 taken during active operations. Photo illustrates the well location, well location access road and the offsite tank battery location. Note- the access road appears to be pre-existing and appears to be used to agricultural activities.

Inspection Photos  
Location Name: KOCHERT #12-18  
Location ID: 310650



**Photo 2.** Photo taken from the associated offsite tank battery, facing North. Photo illustrates final reclamation has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697503114



Inspection Photos  
Location Name: KOCHERT #12-18  
Location ID: 310650



**Photo 3.** Photo taken from the associated offsite tank battery, facing Southeast. Photo illustrates final reclamation has been performed with some desirable vegetation; however, significant patches of Kochia weeds and other desirables were observed. Note- other species were planted that were not observed in reference areas.



Inspection Photos  
Location Name: KOCHERT #12-18  
Location ID: 310650



**Photo 4.** Reference photo taken east of the associated offsite tank battery, facing Southeast. Photo illustrates reference areas are primarily Intermediate wheatgrass, not Smooth brome which was observed at the tank battery.