

Inspection Photos
Location Name: Bredehoft #1
Location ID: 319977



Photo 1 No tracking pad onto HWY 7 from well site.



Photo 2 loc pic

Inspection Photos
Location Name: Bredehoft #1
Location ID: 319977



Photo3 Anchor markers



Photo 4 WH

Inspection Photos
Location Name: Bredehoft #1
Location ID: 319977



Photo 5 TNK BTRY Battery sign missing



Photo 6 graffiti on tank.

Inspection Photos
Location Name: Bredehoft #1
Location ID: 319977



Photo 7 weeds on production facility



Photo 8 production equipment.