

Inspection Photos
Location Name: Bulldog 5-31H-790
Location ID: 428927



Photo 1. Overview of location taken facing south. Annual weeds on location.



Photo 2. Unused equipment stored on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bulldog 5-31H-790
Location ID: 428927



Photo 3. Unused equipment stored on location.



Photo 4. Stained soil on location.

