

Inspection Photos

API: 071-08078

Operator: XTO ENERGY INC

Inspection Date: 8/6/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08078 | Date: 8/6/2021

Inspection Photos



Photo 1. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08078 | Date: 8/6/2021

Inspection Photos



Photo 2. There are two wells that remain at the location. Form 4 notice indicated the HILL RANCH #32-06 well to be plugged and abandoned by 12/31/2018 which has not been performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08078 | Date: 8/6/2021