

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402381385

Date Received:

04/27/2020

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5234

tesla.dougherty@nblenergy.com

Brian Taylor

720-587-2371

Brian.Taylor@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696102775

Inspection Date: 04/22/2020

FIR Submit Date: 04/22/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 331974

Location Name: WARDLAW-66N64W Number: 35SENW County: _____

Qtrqtr: SENW Sec: 35 Twp: 6N Range: 64W Meridian: 6

Latitude: 40.444701 Longitude: -104.519667

FACILITY - API Number: 05-123-00 Facility ID: 331974

Facility Name: WARDLAW-66N64W Number: 35SENW

Qtrqtr: SENW Sec: 35 Twp: 6N Range: 64W Meridian: 6

Latitude: 40.444701 Longitude: -104.519667

CORRECTIVE ACTIONS:

1 ☒ CA# 138250

Corrective Action: Well is overdue for Mechanical Integrity Test.
Produce well after performing successful mechanical integrity test per Rule 326 or plug well.
To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.
Refer to Rule 326.b.

Corrective Action Date: 07/21/2020. Extended due to COVID.

Date: 07/21/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Operator Comment: This well is part of the Alternative MIT AOC (Docket No. 180900672, Order No 1V-668) and it falls under the MIT guidance of that program. As part of the program, the well is tagged with the yellow LTSI tag to indicate that this well is part of that program.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow-up AMI Field Inspection Report Doc #696102981, dated 05/15/2020 confirms that requirement for MIT mitigated per SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE).

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 4/27/2020 11:32:35 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402381385	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files