

Caerus Piceance LLC  
K19NE  
Location # 335338



Location/lack of battery signage



location



Caerus Piceance LLC  
K19NE  
Location # 335338



location



location/lack of labeling on separator baths(glycol)





Caerus Piceance LLC  
K19NE  
Location # 335338



Labeling



Staining



Caerus Piceance LLC  
K19NE  
Location # 335338



**Staining**

