

Inspection Photos

Operator: Catamount/Arkoma
API: 067-05749
Date: 8/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward.



Photo 3. View of musk thistle rosettes remaining untreated within the interim reclamation area. Approximately 100 individuals observed.