


**Inspection Photos**  
**Location Name: Loyd PC GD 33-13**  
**Location ID: 419918**



**Photo 1 – Wellhead – Weeds – Unused Rods/Tubing/Unused Equipment**



**Photo 2 – Gas Engine has been removed**



**Inspection Photos**  
**Location Name: Loyd PC GD 33-13**  
**Location ID: 419918**



**Photo 3 – Wellhead Sign**