

Caerus Piceance LLC
RI 1
Location # 334572



location



location/lack of separator bath signage



Caerus Piceance LLC
RI 1
Location # 334572



Location/lack of battery signage



location



Caerus Piceance LLC
RI 1
Location # 334572



Lack of bull plug/cap



staining



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
RI 1
Location # 334572



Lack of bull plug/cap



Lack of stabilization/compaction

Caerus Piceance LLC
RI 1
Location # 334572



Lack of stabilization/compaction/weeds



Lack of stabilization/compaction/weeds



Caerus Piceance LLC
RI 1
Location # 334572



Lack of stabilization/compaction/weeds



**Access road lack of
stabilization/compaction/erosion**



Caerus Piceance LLC
RI 1
Location # 334572



**Access road lack of
stabilization/compaction/erosion**



**Access road lack of
stabilization/compaction/erosion**

