

Final Reclamation Inspection

August 12, 2021

Operator: FOUNDATION ENERGY MANAGEMENT LLC- #10112

Facility ID: 330670

Inspection Document #: 697503148

Weld County, CO

SWNW Section 32 T8N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 1. Photo taken from the western well location access road, facing East. Photo illustrates Operator has performed final reclamation activities; however, the access road consists mostly of annual vegetation, not reflective of reference perennial vegetation.

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 2. Photo taken from a portion of the well location access road, facing East. See comments under Photo 1.



Photo 3. Photo taken from the eastern well location access road, facing East. See comments under Photo 1.

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 4. Photo taken from the well location, facing East. See comments under Photo 1.



Photo 5. Photo taken from the well location, facing South. See comments under Photo 4.

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 6. Photo taken from the well location, facing West. See comments under Photo 1.



Photo 7. Photo taken from the well location, facing North. See comments under Photo 4.

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 8. Photo taken from the eastern well location access road, facing Southwest. See comments under Photo 1.



Photo 9. Reference photo taken from the well location access road, facing North. Photo illustrates the reference area vegetation of blue grama and buffalo grass.

Inspection Photos
Location Name: SHOWERS #32-5-7
Location ID: 330670



Photo 10. Photo taken from the associated offsite tank battery, facing West. The tank battery is being addressed under a separate inspection.