

Inspection Photos

8/13/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 312736

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312736



Photo 1: Aerial imagery of the Location pre- O&G disturbance (left, 2006), and post-O&G disturbance (Right, 2016). Road pre-existed construction of the Location. Photo also shows areas (right photo, yellow polygon) that have not been reclaimed/revegetated, and gravel remains.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312736



Photo 2: Photo taken from the north end of the Location (North of the tank battery). Photo shows noxious weeds (Canada thistle) established on the interim areas of the Location. Plants have matured and are currently seeding out.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 312736



Photo 3: Photos taken from the west end of the Locating, facing east/southeast. Photos show Location does not meet COGCC 1004 reclamation requirements; gravel base remaining; areas not revegetated;