

Inspection Photos

8/03/2021

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 425092

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 425092



Photo 1: Photo taken from the Location. Photo shows Location is not progressing towards COGCC 1004 uniform vegetative standards and requirements; Large areas of the Location remain predominantly bare soil.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 425092



Photo 2: Photo taken from the Location. Photo on left shows wattles on the Location are not in proper functioning condition, and are considered debris. Photo on the right shows example of erosion degradation observed on the Location. Stormwater and erosion control BMPs missing or insufficient on the Location.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 425092



Photo 3: Photo provides example of noxious weeds (Musk thistle, Bindweed), observed on Location and access road.