

Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 1. Overview of location taken facing west.



Photo 2. Tank labels peeling. Annual and noxious weeds on location.



Inspection Photos
Location Name: Dwinell 1
Location ID: 324591



Photo 3. Well shut in at time of inspection.



Photo 4. 50 psi on injection tubing.

