

Inspection Photos
Location Name: Federal 2-25
Location ID: 313015



Photo 1. Overview of location taken facing north.

Inspection Photos
Location Name: Federal 2-25
Location ID: 313015



Photo 2. Signs still have previous operator information. No bradenhead access apparent.



Photo 3. Signs still have previous operator information.



Inspection Photos
Location Name: Federal 2-25
Location ID: 313015



Photo 4. Sediment migration on access road.



Photo 5. Sediment migration on overgrown access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources