

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV PAD /7K

Location ID: 334366



Photo #4808 from entrance to location.



Photo #4809 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC SGV PAD /7K

Location ID: 334366



Photo #4810 Location lacks stabilization.



Photo #4811 No form of tracking BMP located at the entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources