

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1SESE

Location ID: 334948



Photo #4837 from entrance to location.



Photo #4838 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1SESE

Location ID: 334948



Photo #4839 No battery sign located at the tank battery.



Photo #4840 Separators missing required information.