

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324154



Photo #4841 from entrance to location.



Photo #4842 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324154



Photo #4843 No battery sign located at the tank battery.



Photo #4844 Separator missing required information.



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324154



Photo #4846 Wellhead sign weathered and not legible.



Photo #4845 Separator missing bird protector.