

Inspection Photos
Location Name: Ocoma 31-17
Location ID: 327685



Photo #1 Access Road is overgrown in vegetation/weeds



Photo #2 Access Road is overgrown in vegetation/weeds

Inspection Photos
Location Name: Ocoma 31-17
Location ID: 327685



Photo #3 Access Road is overgrown in vegetation/weeds



Photo #4 Weeds, Torn down fence & Well



Inspection Photos
Location Name: Ocoma 31-17
Location ID: 327685



Photo #5 Weeds, Torn down fence & Well

