

Inspection Photos
Location Name: Ocoma 31-25
Location ID: 247879



Photo #1 Well and Torn down fence



Photo #2 Well & Torn down fence



Inspection Photos
Location Name: Ocoma 31-25
Location ID: 247879



Photo #3 Leaking casing nut on threads



Photo #4 Leaking casing nut on threads

