

Inspection Photos
Location Name: Horth 41-15-1
Location ID: 310112



Pic 1 Tank battery, weeds unmanaged.



Pic 2 spill behind tank battery approx. size 26' X 8'

Inspection Photos
Location Name: Horth 41-15-1
Location ID: 310112



Pic 3 possible underground leak from flowline



Pic 4 opposite side of buried vault water tank spill.

Inspection Photos
Location Name: Horth 41-15-1
Location ID: 310112



Pic 5 gas meter run, weeds unmanaged.



Pic 6 separator, weeds unmanaged.

Inspection Photos
Location Name: Horth 41-15-1
Location ID: 310112

Aug 20, 2021 at 10:14:48 AM
39.969243,-104.529574
Teenesburg CO 80643
United States
COGCC



Pic 7 ECD, weeds unmanaged.

Aug 20, 2021 at 10:15:16 AM
39.969243,-104.529574
Teenesburg CO 80643
United States
COGCC



Pic 8 trash inside separator house.

Inspection Photos
Location Name: Horth 41-15-1
Location ID: 310112

Aug 20, 2021 at 10:19:11 AM
39.968883,-104.529918
Keenesburg CO 80643
United States
COGCC



Pic 9 weeds unmanaged.

Aug 20, 2021 at 10:36:41 AM
39.968922,-104.529884
Keenesburg CO 80643
United States
COGCC



Pic 10 weeds unmanaged.