

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314



Pic 1 spill from top of oil tank



Pic 2 spill from top of tank

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314

Aug 20, 2021 at 12:36:47 PM
39.975647,-104.529825
Greeensburg CO 80643
United States
COGCC



Pic 3 weeds, and trash around separator, and small building.

Aug 20, 2021 at 12:36:51 PM
39.975647,-104.529825
Greeensburg CO 80643
United States
COGCC



Pic 4 gas meter run weeds unmanaged.

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314



Pic 5 open pit, weeds unmanaged.



Pic 6 open pit, weeds unmanaged.

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314



Pic 7 poly hose on location



Pic 8 storage of chemicals in small building on location, no containment under chemicals.

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314



Pic 9 poly hose unused on location



Pic 10 debris/trash/unused small building on location.

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314



Pic 11 flow manifold next to separator.



Pic 12 debris on location

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314




Pic 13 debris on location



Pic 14 debris on location

Inspection Photos
Location Name: Abbott 43-10
Location ID: 320314

Aug 20, 2021 at 12:44:05 PM
39.976137,-104.529816
Greenesburg CO 80643
United States
COGCC



Pic 15 wellhead some weed growth.