

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/19/2021

Submitted Date:

08/24/2021

Document Number:

688311157

**FIELD INSPECTION FORM**Loc ID 309600 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10581

Name of Operator: ABILENE PERFECT ENERGY JV LLC

Address: 4600 PECOS STREET

City: DENVER State: CO Zip: 80211

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gonzalez, Patricia		patricia@perfectenergy.us	
Lindley, Trent		trent.lindley@state.co.us	
malick		malick@perfectenergy.us	
Jacobson, Eric		eric.jacobson@state.co.us	
Kosola, Jason		jason.kosola@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218179	WELL	PR	05/20/2013	OW	073-06164	1-6 S-S-M MELLOTT 1	TA

**General Comment:**

TA Well, no current MIT

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	No sign anywhere.		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	08/24/2021

Emergency Contact Number:

Comment: No sign, no emergency contact info

Corrective Action:  Date:

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Heater Treater	# 1		
Comment:	rusted out, see attached photo		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 218179 Type: WELL API Number: 073-06164 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is incapable of production in current status, i.e., no production equipment, no tanks, treated is rusted out, no pumping unit or pluger, no casing production. Last produced 12/1/2015, TA since 2/1/2016.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 09/24/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311190	Abilene Perfect Energy Mellott 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513907">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5513907</a>