

# Inspection Photos

API: 073-06739

Operator: K3 OIL & GAS OPERATING

Inspection Date: 8/24/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 073-06739 | Date: 8/24/2021

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road. The cattleguard remains and the fence has not been put back to original place. The road entrance was widening and needs to be put back to pre-existing condition.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 2.** Facing northeast toward the location. The perimeter of the location is fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021



## Inspection Photos



**Photo 3.** Center of the location facing north. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021



## Inspection Photos



**Photo 4.** Center of the location facing west. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021



## Inspection Photos



**Photo 5.** Center of the location facing south. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021



## Inspection Photos



**Photo 6.** Center of the location facing east. The location has not established desirable vegetation and consists mostly of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021



## Inspection Photos



**Photo 7.** View of ground cover shows undesirable vegetation growth (Kochia). Desirable vegetation has not established..



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021