

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NWSW

Location ID: 335436



Photo #4855 from entrance to location.



Photo #4856 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /34NWSW

Location ID: 335436



Photo #4857 Location lacks stabilization.



Photo #4858 No form of tracking BMP located at the entrance of location.