

Inspection Photos
Location Name: Paul Heinze #1 Flowline
Spill IDs: 479232, 480128 Remediation: 18954



Photo 1 – Excavation of spill ID 479232 overview.
Note fencing down throughout excavation.



Photo 2 – Spill 480128 release area.

Inspection Photos

Location Name: Paul Heinze #1 Flowline

Spill IDs: 479232, 480128 Remediation: 18954



Photo 3 – Trash left on location.



Photo 4 – Trash left on location.