

Inspection Photos

API: 025-06020

Operator: CRAZY 8 ENERGY LLC

Inspection Date: 8/23/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 1. Facing north toward the location. The area around the location has been mowed. There is tall weedy vegetation at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 2. Facing north at the east side of the location. A portion of the location was mowed and the rest of the location was left with tall undesirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 3. Facing north at the west side of the location. A portion of the location was mowed and the rest of the location was left with tall undesirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 4. Facing northeast at the east side of the location. A portion of the location was mowed and the rest of the location was left with tall undesirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 5. View of vegetation cover at the location which consists mostly of undesirable weeds such as Kochia, Barnyard grass, Bindweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 6. Facing south toward the area surrounding the location. The surrounding area was also partly mowed and consists of undesirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021

Inspection Photos



Photo 7. Facing west toward the area surrounding the location. The surrounding area was also partly mowed and consists of undesirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 025-06020 | Date: 8/23/2021