

Inspection Photos

8/23/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324441

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324441



Photo 1: Photo taken from the Location. Photos show additional controls have been implemented to stabilize the access road and production areas.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 324441



Photo 2: Photo on left taken from the soil stockpile on the northeast end of the Location. Photo right taken from the interim areas on the west end of the Location. Photos show examples of Undesirable Plant Species (*Kochia* sp., *Salsola* sp., etc...) that remain evident/established on the Location; noxious weeds were not observed during inspection; Reclamation Specialist acknowledges that additional weed management appears to have been performed, however, Location remains out of compliance with Rule 606.c



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 324441



Photo 3: Photo taken from the south end of the Location, facing west. Photo shows Operator has further reduced/reclaimed areas on the south end of the Location not necessary for production.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources