

Inspection Photos

8/23/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 323893

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 323893



Photo 1: Photos taken from the south end of the Location. Photos reclamation of the southern access roads was in process at time of inspection. Corrective action will remain applicable until work has been completed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 323893



Photo 2: Photo taken from the reclaimed access road on the north end of the Location. Photos show control measures to protect and stabilize the reclaimed areas remain missing or insufficient/inadequate. Photos also show that Operator appears to have mixed topsoils with rocky subsoils during the reclamation of this road. Photo on right shows example of topsoil observed on the adjacent areas (arrow).

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 323893



Photo 3: Photos taken from the reclaimed access road on the north end of the Location. Photos show control measures to protect and stabilize the reclaimed areas remain missing or insufficient/inadequate. Photos also show that Operator appears to have mixed topsoils with rocky subsoils during the reclamation of this road.