

Inspection Photos

8/23/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 335815

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 1: Photo taken from the north of the Location, and provides an overview of the total disturbance area. Photo show interim reclamation of the Location has not been conducted in accordance with 1003 Rules

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 2: Photos 2-3 taken from the north end of the Location. Photos provide an overview of the Location from southeast, south, southwest to west. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 Rules

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 3: Photos 2-3 taken from the north end of the Location. Photos provide an overview of the Location from southeast, south, southwest to west. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 4: Photos 4-5 taken from the southeast end of the Location. Photos provide an overview of the Location from west, northwest, to north. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



August 23, 2021
39.53267904N 108.24221697W

Photo 5: Photos 4-5 taken from the southeast end of the Location. Photos provide an overview of the Location from west, northwest, to north. Photos show interim reclamation of the Location has not been conducted in accordance with 1003 Rules.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 6: Photos show example of slopes on the Location. BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 7: Photos show example of slopes on the Location. BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 335815



Photo 8: Photos show example of slopes on the Location. BMPs to protect and stabilize the slopes of the Location remain missing or insufficient/inadequate.