

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402787512

Date Received:

08/30/2021

Spill report taken by:

Araza, Steven

Spill/Release Point ID:

480397

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: <u>SUMMIT MIDSTREAM PARTNERS LLC</u>	Operator No: <u>200565</u>	<b>Phone Numbers</b>
Address: <u>999 18TH STREET #2500S</u>		Phone: <u>( )</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>		Mobile: <u>(701) 3391720</u>
Contact Person: <u>harold rhodes</u>		Email: <u>harold.rhodes@summitmidstream.com</u>

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402778246

Initial Report Date: 08/12/2021 Date of Discovery: 08/12/2021 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR SE SE SEC 6 TWP 7S RNG 92W MERIDIAN 6Latitude: 39.470000 Longitude: -107.702000Municipality (if within municipal boundaries): \_\_\_\_\_ County: GARFIELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: GAS GATHERING PIPELINE SYSTEM☐ Facility/Location ID No \_\_\_\_\_Spill/Release Point Name: P6 Lateral near GR12 Well Pad☐ Well API No. (Only if the reference facility is well) 05- -☒ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: \_\_\_\_\_

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): \_\_\_\_\_

Weather Condition: Sunny, 76 degrees, NE 4 mphSurface Owner: OTHER (SPECIFY)Other(Specify): BJM, Ltd

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

After pressuring up the P6 Lateral for a pressure test, the pipeline operator noticed the pressure dropping on the line. He drove the ROW looking for signs of a leak and found a spot where the vegetation was starting to die. He verified the leak with the FLIR camera (OGI device). There is no liquid on the ground. This line is an 8 inches in diameter and 1,320 ft. long. The GPS coordinates for the leak are -107.702 and 39.470. The Operator locked out the line and blew it down. We will schedule a line repair with construction.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
8/12/2021	Colorado Parks & Wildlife	Scott Hoyer Voice Mail	970-2500873	None for now
8/12/2021	Garfield County EMS	Dispatcher	970-9450453	None for now
8/13/2021	Land Owner	BJM Ltd.	970-6180371	None for now

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_
- Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_
- Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 08/23/2021		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, <b>including walls &amp; floor regardless of construction material</b>, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>31</u>		Width of Impact (feet): <u>22</u>	
Depth of Impact (feet BGS): <u>17</u>		Depth of Impact (inches BGS): _____	
How was extent determined?			
Field determination of of lateral and vertical extents initially identified using PID meter, SC meter and HACH Quantabs. Confirmation samples will be submitted to lab for lab analysis.			
Soil/Geology Description:			
0-60" soils consistent with Potts Loam, sub soils consistent with alluvial subsoils.			
Depth to Groundwater (feet BGS) <u>100</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>3376</u> None <input type="checkbox"/>	Surface Water <u>3126</u> None <input type="checkbox"/>	
	Wetlands <u>4096</u> None <input type="checkbox"/>	Springs <u>2515</u> None <input type="checkbox"/>	
	Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>3398</u> None <input type="checkbox"/>	
Additional Spill Details Not Provided Above:			
Photograph included depicting disturbed area and excavation. lab samples have been submitted to the lab.			

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

Initial clean up complete pending confirmation samples

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: harold rhodes

Title: env remed Date: 08/30/2021 Email: harold.rhodes@summitmidstream.com

### Condition of Approval

#### COA Type

#### Description

0 COA

### Attachment List

#### Att Doc Num

#### Name

402787512	SPILL/RELEASE REPORT(SUPPLEMENTAL)
402795580	PHOTO DOCUMENTATION
402797265	FORM 19 SUBMITTED

Total Attach: 3 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Comply with COAs listed on doc #402778246.	08/31/2021
Environmental	Per Rule 912.b.(4), the Operator will file a Form 19 - Supplemental report not more than 10 days after the spill or release was discovered. The Discovery Date for this spill is 8/12/2021 and this Supplemental Form 19 was not received until 8/30/2021.  Note to Operator: failure to comply with Rule 912 Spill Reporting criteria may result in penalty enforcement action.	08/30/2021

Total: 2 comment(s)