

Inspection Photos
Location Name: Simpson 25-4
Location ID: 313400



Photo 1. Overview of location taken facing northeast. Weeds on location.



Inspection Photos
Location Name: Simpson 25-4
Location ID: 313400



Photo 2. No bradenhead access apparent. Annual weeds on location.



Photo 3. Noxious weeds on location.

