

Inspection Photos
Location Name: Mc Williams 2-31
Location ID: 312949



Photo 1. Overview of location taken facing south. Annual weeds on location.



Photo 2. No bradenhead access apparent. Wellhead sign knocked over.



Inspection Photos
Location Name: Mc Williams 2-31
Location ID: 312949



Photo 3. Annual weeds on location. Pit.




Photo 4. Meter not calibrated annually/calibration not displayed.